

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

EDR ID Number  
EPA ID Number

AI184  
South  
1/4-1/2  
0.316 mi.  
1667 ft.  
MANHOLE #42404  
SURF AVE AT WEST 12 ST  
BROOKLYN, NY  
Site 6 of 8 in cluster AI

NY Spills S107416244  
N/A

Relative:  
Higher

Actual:  
6 ft.

SPILLS:

Name: MANHOLE #42404  
Address: SURF AVE AT WEST 12 ST  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 0508724 / 2005-11-23  
Facility ID: 0508724  
Facility Type: ER  
DER Facility ID: 301705  
Site ID: 354367  
DEC Region: 2  
Spill Cause: Unknown  
Spill Class: Not reported  
SWIS: 2401  
Spill Date: 2005-10-20  
Investigator: GDBREEN  
Referred To: Not reported  
Reported to Dept: 2005-10-20  
CID: 409  
Water Affected: Not reported  
Spill Source: Unknown  
Spill Notifier: Local Agency  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 2005-10-20  
Spill Record Last Update: 2005-11-23  
Spiller Name: ERT DESK  
Spiller Company: CON EDISON  
Spiller Address: MH 42404  
Spiller Company: 999  
Contact Name: ERT DESK MIKE DAUGHTERY

DEC Memo: "161586. 10/20/05 17:15 HRS. G. ROSALIE #14570 FOD REPORTS FINDING APPROX 1/2 GAL OF UNKNOWN OIL ON APPROX 600 GALS OF WATER IN M42404. THIS WAS FOUND WHILE LOCATING A FAULT ON FDR 7B04 ON ACCT# C3242. THERE WAS NO SMOKE, FIRE, OR INJURIES, RELATED TO THE SPILL, NOR WERE ANY SEWERS, WATERWAYS, OR PRIVATE PROPERTY AFFECTED. THE SOURCE AND CAUSE OF THE SPILL IS UNKNOWN. HOWEVER THERE WERE CONTRACTORS ON LOCATION WHO WERE DIGGING NEW WATER MAINS AND IN THE PROCESS THEY PULLED UP THE FEEDER, AND AS A RESULT APPROX 30 GALS OF THE WATER FROM THE MANHOLE DRAINED INTO THE CONTRACTORS TRENCH. THE WATER IN THE STRUCTURE IS CURRENTLY STANDING STILL, AND THE EXISTENCE OF ANY SUMPS, DRAINS, OR SEWER CONNECTIONS COULD NOT BE VERIFIED AT THIS TIME. ENV STOP TAG#31307 WAS PLACED, AND ONE LIQUID SAMPLE TAKEN ON E PRIORITY FOR PCB ANALYSIS ON CHAIN OF CUSTODY #DD03542. THE SAMPLE WILL BE TAKEN TO CHEM LAB BY G. ROSALIE AND CLEANUP IS PENDING RESULTS. J ANDERSON Closed. 11-23-05. see eDocs. GB "

Remarks: "LOCATED ON 600 GAL OF WATER.CON ED#161586. CLEAN UP IS PENDING REULTS OF SAMPLE TAKEN."

All Materials:  
Site ID: 354367

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Operable Unit ID: 1111781  
Operable Unit: 01  
Material ID: 2101827  
Material Code: 0066A  
Material Name: unknown petroleum  
Case No.: Not reported  
Material FA: Petroleum  
Quantity: 1.00  
Units: G  
Recovered: .00  
Oxygenate: Not reported